WEST

Thank you for choosing Westin products

for additional installation assistance please call

Customer Service (800) 793-7846


## **INSTALLATION INSTRUCTIONS**

STEP BOARD MOUNT KIT

#### APPLICATION: 2024 TACOMA XTRACAB / DOUBLE CAB

# PART NUMBER: 27-2785

CONTENT			
ITEM	QUANTITY	DESCRIPTION	TOOLS NEEDED
1	1	DRIVER MOUNT BRACKET 'A'	13mm SOCKET
2	1	PASSENGER MOUNT BRACKET 'A'	RATCHET
3	2	DRIVER MOUNT BRACKET 'B'	TORQUE WRENCH
4	2	PASSENGER MOUNT BRACKET 'B'	
5	12	M8 HEX HEAD BOLT	
6	12	M8 SQUARE HEAD BOLT	
7	24	M8 FLAT WASHER	
8	12	M8 SPLIT LOCK WASHER	
9	12	M8 NYLON LOCK NUT	
ANTI-SEIZE LUBRICANT MUST BE USED ON ALL STAINLESS STEEL FASTENERS TO PREVENT THREAD DAMAGE AND GALLING			





P.N.: 75-272785-RevA

ECO #:W23-0110

320 W. Covina Blvd


San Dimas, Ca. 91773

Westin Automotive Products, Inc.


#### PROCEDURE


- Remove contents from box, verify if all parts listed are present and free from damage. Carefully read and understand all instructions before attempting installation.
  Failure to identify damage before installation could lead to a rejection of any claim.
- 2. Starting with the drivers side, locate and install the Driver Mount Bracket 'A' (item 1) using the M8 hardware (items 5, 7, and 8). See Figures 1 & 2.






Locate and install (2) Driver Mount Bracket 'B' (item 3) using the M8 hardware (items 5, 7, and 8). See Figures 3 &4.
Repeat steps 2 and 3 on the passenger side of the vehicle.










Thank you for choosing Westin products for additional installation assistance please call Customer Service (800) 793-7846 www.westinautomotive.com DATE: 4/4/24 For Grate Steps Running Boards, refer to the installation sheet included with the running boards.

For SG6, Sure-Grip, and Molded Running Boards, refer to Steps 5-8.

- 5. Lay the running boards on top of the brackets.
- 6. Slide (12) M8 square head bolts (**item 6**) through slots on the bottom of the running board (excluding the center slot, three bolts per slot).
- 7. Loosely install (12) M8 flat washers (item 7) and (12) M8 nylon lock nuts (item 9). See Figure 5.
- 8. Align and adjust the running board as needed and fully tighten all hardware. Torque all M8 fasteners to 15-18 ft-lbs.





#### CARE INSTRUCTIONS

- REGULAR WAXING IS RECOMMENDED. DO NOT USE ANY TYPE OF POLISH OR WAX THAT MAY CONTAIN ABRASIVES.
- STAINLESS STEEL PRODUCTS CAN BE CLEANED WITH MILD SOAP AND WATER. STAINLESS STEEL POLISH SHOULD BE USED TO POLISH SMALL SCRATCHES.
- GLOSS BLACK FINISHES SHOULD BE CLEANED WITH MILD SOAP AND WATER.



Westin Automotive Products, Inc. 320 W. Covina Blvd San Dimas, Ca. 91773

Thank you for choosing Westin products for additional installation assistance please call Customer Service (800) 793-7846 www.westinautomotive.com DATE: 4/4/24







Failure to follow these instructions could lead to death, personal injury, and / or property damage.

Failure to follow these instructions could lead to death, personal injury, and / or property damage.

#### FASTENERS:

All Westin supplied fasteners must be utilized and installed in accordance with the installation instructions and apply torque to the specifications as defined. DOUBLE CHECK ALL FASTENERS BEFORE INITIAL USE, AND PERIODICALLY IN THE FUTURE TO ENSURE PROPER FUNCTION AND SAFETY.

#### DRILLING:

Most Westin products do not require drilling for installation. If drilling is defined as required, use caution when drilling a vehicle. FAILURE TO REVIEW AN AREA TO BE DRILLED MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

#### EYE PROTECTION:

ALWAYS WEAR SAFETY GLASSES OR GOGGLES DURING THE INSTALLATION PROCESS TO AVOID PERSONAL INJURY.

### MAXIMUM TOWING/CARRYING CAPACITY: (if applicable)

The Westin Receiver Hitches will have a visible tow rating label affixed directly on the product. User should never exceed the vehicle manufacturers maximum tow and weight rating regardless of the capacity of the hitch. FAILURE TO FOLLOW THESE GUIDELINES WILL VOID THE WESTIN WARRANTY AND MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

FOR CALIFORNIA RESIDENTS ONLY-PROP 65 WARNING:

Some products may contain chemicals such as DEHP, which can cause cancer, birth defects or other reproductive harm. For more info go to www.p65warnings.ca.gov



Westin Automotive Products, Inc. 320 W. Covina Blvd San Dimas, Ca. 91773